DATE REVISED: 9/5/18 DATE ISSUED: DATE REVISED: ATE REVISED: 2/8/18 DATE REVISED: 2/19/18 DATE REVISED: 3/5/18 DATE REVISED:

THE USE OF THESE PLANS IS LIMITED TO ANY THE ORGANAL SITE PLANS WERE ISSUED ANY REPRODUCTION OF DISTRIBUTION IS OF PRESSAY. UMBER TO SOUR OUSE, MAY OTTER PRODUCTION, REUSE, DR DISTUEDRE IN THESE DRAWMS CONTAIN PROPRIET INFORMATION AND THE REMAINS IN MASTERPLANS, DENNIS C. HILBORN MASTERPLANS, DENNIS C. HILBORN

KELLER, TEXA/

 $\begin{array}{c} MasterPlans \\ 817-379-7326 \\ \text{\tiny © COPYRIGHT 2018 DENNIS C. HIBORN} \end{array}$

JOHNSON WK SHOT 17-114



4/I2 TILE

4/I2 TILE

ROOF PLAN

SCALE 1/6° = 1'-0°

€ I/I2 METAL

THESE DRAWINGS, FOR THIS DESIGN, HAVE BEEN DEVELOPED AND ISSUED WITHOUT SPECFIFIC KNOWLEDGE OF GEOGRAPHIC LOCATION, THEREPOSE SUPPLIENTIAL TO THESE DOCUMENTS ITS THE RESPONSIBILITY OF DRAWINGS FERREL SAND PRAVINGS FERREL CONTRACTION TO RANDING ENGINEER DAY SPECFIFIC SHOP DRAWINGS FERREL STRUCKINGS, AND OTHER AREAS REQUIRED BY THE LOCAL TOWNINGS FOR THE COUNTRACTIONS, AND OTHER AREAS REQUIRED BY THE LOCAL TOWNINGS OF THESE PLANS.

IT INTO OWNERS, GEN. CONTRACTIONS, AND FITTESS OF PURPOSE OF THESE PLANS.

ILBURY SHALL MOT EXCEED THE PRICE PLAN TO MASTERPLANS FOR THESE PLANS.

JOHNSON MK SHOP

MasterPlans 817-379-7326 © COPYRIGHT 2018 DENNIS C. HILBORN

ATE REVISED:

PATE REVISED:

PATE REVISED:

PATE REVISED:

PATE REVISED:

PATE REVISED:


THE USE OF THESE PLANS IS LIMITED TO ONLY THE RORGINAL, SITE PLANS WERE ISSUED. ANY REPRODUCTION OR DISTRIBUTION IS EXPRESSLY LIMITED TO SUCH USE. ANY OTHER REPRODUCTION, REUSE, OR DISCLOSURE BY ANY METHOR IN WHOLE OR IN PART, IS PROHIBITED. THESE DRAWNIGS CONTAIN PROPRIETARY INFORMATION AND TITLE REMAINS IN


JOHAJON WORKJHOP

KELLER, TEXA

CONSTRUCTION DRAMINGS

2/7/18





CONSTRUCTION DRAMINGS


JOHAYON WORK/HOP


MasterPlans 817-379-7326 © copyright 2018 DENNIS C. HILBORN

DATE REVISED:

DATE REVISED: DATE REVISED: DATE REVISED:

JOHNSON WK SHOF





Jerald Ducay

From:

David Johnson <daviduj777@verizon.net> Monday, October 15, 2018 2:55 PM Jerald Ducay

Sent:

To:

Subject:

!565 Nightingale Cir. (SUP)

The total exposed garage door square feet is 264. Each door size is 11x12 = 132 Sqft.





This is the type of material the applicant is proposing to emulate with the accessory structure (Stucco / Spanish Tile roofing)

4	



4200 N. Main, Ste. 150 Fort Worth, TX 76106



JULY 25, 2018

JOHNSON CONSTRUCTION

GENTLEMEN,

THE FOUNDATION PLANS, ACCOMPANIED BY THIS LETTER, AS DESIGNATED BY IAN NORFOLK, P.E., ARE AUTHORIZED FOR USE ONLY UPON THE PROPERTY DESCRIBED BELOW:

DESCRIPTION:

SINGLE FAMILY RESIDENCE - WORKSHOP ADDITION

DESIGN CODE:

WHITWORTH ENGINEERING REPORT NO. ST18-0162, 03/17/18

PI: 25

QU: 890 PSF

LOT/BLOCK:

9/1

SUBDIVISION:

FLORENCE PLACE ADDITION

ADDRESS:

1565 NIGHTINGALE CIRCLE

KELLER, TEXAS

JOB NO.:

WE18-0972

FOUNDATION DESIGN CRITERIA WAS FORMULATED BASED ON MODIFICATIONS OF RECOMMENDATIONS AS SET FORTH IN CRITERIA FOR SELECTION AND DESIGN OF SLAB-ON-GROUND (BRAB AND/OR WRI REPORT), ACI 318-99, IRC 2009, IRC 2012, IRC 2015, AND RECOGNIZED ENGINEERING PRACTICES.

NOTE: ACCOMPANYING "OWNER MOISTURE MAINTENANCE LETTER" IS TO BE TRANSMITTED TO OWNER, WITH OWNER'S RECEIPT ACKNOWLEDGED TO BUILDER/CONTRACTOR.

SINCERELY

IAN NORFOLK, P.E.



The seal appearing on this document was authorized by Ian Norfolk, P.E. 93550
Whitworth Engineering F-3973



FOUNDATION MOISTURE MAINTENANCE

PROPERTY OWNER:

Structures built on ground supported concrete foundations depend not only on proper design and construction, but also on proper foundation environment maintenance performed by the occupant or owner of the property. A properly designed and constructed foundation may still experience distress if the surrounding soils are not being properly cared for. Active soils are any type of soil that, when exposed to certain conditions, will undergo shrinking and swelling. In areas such as Dallas/Fort Worth, where active soils are present, excessive moisture or too little moisture can affect the condition of the foundation. The objective of a proper maintenance program is to maintain as near constant moisture content, as possible, for the soil under the foundation.

The following is a list of items to be considered when planning proper foundation maintenance:

- Drainage
- Never allow water to pond near or against foundation slabs.
- Maintain positive drainage away from the foundation. The minimum slope shall be 5% for a distance of 10 feet from the edge of the foundation. (5% equals a 6 inch drop in 10 feet)
- Where a horizontal distance of 10 feet is not possible a berm or swale shall be constructed which provides a minimum 1% slope conveying the water to an acceptable outfall.
- The installation and maintenance of gutters and downspouts are highly recommended, they should be kept clear and discharge water away from the foundation.

2. Landscaping:

- There should be a minimum distance of 6 inches between the top of the slab and the ground.
- Landscape beds must also maintain the minimum positive slope of 5% away from the foundation.
- Where landscape beds are placed adjacent to the foundation they should be equipped with a moisture barrier and/or area drains which convey water by means of buried pipe to an acceptable outfall.
- Area drains must be checked periodically to ensure that they remain functional.
- Trees remove moisture from the ground in order to survive, and should therefore be watered regularly.
- Trees should be placed at a distance no closer to the foundation than the full height of the mature tree.
- If existing tree removal is not an acceptable option, a root guard system should be constructed around the foundation in the area of the tree(s). Replace and compact any loose fill adjacent to the foundation with native soil: Water is conveyed quickly through sand or granular materials, these materials should not be used adjacent to the foundation unless accompanied by an appropriate drain system.

3. Seasonal Changes:

- Avoid excessive drying around the perimeter of the foundation: when soil pulls away from foundation it is too dry.
- Excessive moisture is also a problem, therefore avoid over watering, even during dry seasons.
- 4. Swimming pools, pipe systems and sprinkler lines:
 - Routinely check for leaks.

All property owners should conduct a yearly survey of their foundation and perform any maintenance necessary to improve drainage and prevent the ponding of water adjacent to these structures. This is especially important during the first ten (10) years after construction because this is usually the time when the most severe adjustment between the new foundation and its supporting soil occurs.

Sincerely,

Russell J. Whitworth, P.E.

Owner's Signature

